

VERZEICHNIS DER AUSGEFÜHRTEN HERSTELLERANWEISUNGEN (OHNE LTA)
BAUMUSTER: CZAW/ZENITHAIR CH601XL-B SERIE-NR.: 6-9790
Stand: 18.02.2018

| Herstellieranweisung | Aussteller | Datum | Fälligkeitsintervall | Gegenstand, Art der Durchführung | Ausgeführt | |
|---------------------------------------|----------------|------------|------------------------|--|------------|-------|
| | | | | | Am | Durch |
| Standard Modification SM10366 | LAA, UK | 26.06.1905 | Before first flight | Reduced Friction in Elevator Circuit | | pom |
| Approved Modification | Zenithair, USA | 25.03.2008 | Before first flight | Elevator Deflection Stop Update | | pom |
| Airworthiness Notice 070109-1 Issue 1 | RAA, Australia | 13.01.2009 | Before next flight | Compulsory Fitment of a Secondary Canopy Locking Device | | |
| Service Letter ZE-2009-01 | Zenair Europe | 01.06.2009 | Before next flight | Verification of the proper installation of the "Flap Stops" (Part No 6S3-1) | | |
| Service Letter ZE-2009-02B | Zenair Europe | 02.06.2009 | As soon as practicable | Alternative design for a fuselage-mounted aileron stop (a.k.a. Torque Tube Stop) | | pom |
| Notice to Owners ZE-2009-03 | Zenair Europe | 31.07.2009 | n/a (ULM only) | Clarification of aircraft speeds - for updating Flight Manual (POH) | | |
| Safety Notice ZE-2009-04 | Zenair Europe | 22.11.2009 | Before next flight | Actions and upgrades from AMD Safety Alert/Safety Directive (November 07, 2009, FAA SAIB CE-10-08) | | pom |
| Service Letter ZE-2009-05 | Zenair Europe | 24.11.2009 | n/a (ULM only) | Aileron bellcrank stiffeners for the CH601XL/CH650E | | |
| Service Letter ZE-2009-06 | Zenair Europe | 25.11.2009 | n/a (ULM only) | Aileron counter-balance weights | | |
| Service Letter ZE-2009-07 | Zenair Europe | 04.12.2009 | n/a (ULM only) | Airframe upgrades for ULM versions of the CH601XL/CH650E | | |
| Zenithair Safety Alert - SEP 2013 | Zenithair, USA | 01.09.2013 | n/a (CH650 only) | Rudder pedal deformations | | |
| Service Letter - AUG 2015 | Zenithair, USA | 01.08.2015 | Recommended | Recommended to change the bungee yearly | | |
| Service Letter - JAN 2016 | Zenithair, USA | 01.01.2016 | Annual, ongoing | Wing strut and general corrosion inspection, lubrication and general maintenance | | pom |
| Notification - DEZ 2016 | Zenithair, USA | 01.12.2016 | Annual, ongoing | Bungee Pin at nose gear. Touching the nose gear strut. | | |
| Safety Alert - JAN 2017 | Zenair, Canada | 01.01.2017 | Annual, ongoing | Inspection of the Horizontal Stabilizer Tail attachment brackets | | |
| Service Letter - FEB 2018 | Zenair, Canada | 01.02.2018 | Annual, ongoing | Fuel system | | |
| Service Bulletin ZE-2008-01 | Zenair Europe | 28.10.2018 | Every 50 h | Verification and adjustment of control cables for adequate tension | | |